



# TalegaonDabhade Municipal Council

Plot 1-5, Laxmibaug Colony, Station Road, TalegaonDabhade, Tal: Maval, Dist: Pune. PIN: 410 506

Establishment: 1988

Contact No: 02114-222449E-mail: talegaondabhademc@gmail.com



Ref. No. : 3761/2021-22

Date: August 3, 2021

## SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

It is certified that, an inspection team headed by Mr. Mayur M.Misal (Sanitary Inspector) from Talegaon Dabhade Municipal Council inspected Shri Parshwa pradnyalay Dnyan Sanskar Mandir, near CRPF, TalegaonDabhade, Tal: Maval, Dist: Pune on August 03, 2021 and found that the Shri Parshwa pradnyalay Dnyan Sanskar Mandir has safe water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitary conditions in the school building and the campus as per the norms prescribed by the Central / State Government.

This Certificate is valid for the period from August 03, 2021 to August 02, 2022.

This certificate is issued on demand by The Principal, Shri Parshwa pradnyalay Dnyan Sanskar Mandir with reference to letter no. 5290 dated 30/07/2021.

  
Mr. Mallikarjun Bansode,  
Water Supply Engineer,  
TalegaonDabhade M. C.



  
Mr. Mayur M. Misal,  
Sanitary Inspector,  
TalegaonDabhade M. C.

Shri Parshwa pradnyalay Dnyan  
Sanskar Mandir

  
Principal

Copy To:  
The Principal,  
Shri Parshwa pradnyalay Dnyan Sanskar Mandir  
Near CRPF, TalegaonDabhade,  
Tal: Maval, Dist: Pune.

  
Chairman  
Shri Parshwa Pradnyalay  
Jain Shwetambar Tirth Pedhi  
Talegaon Dabhade 410506